

RECEIVED

FEB 01 1993

DIVISION OF
OIL GAS & MINING

STATE OF UTAH
DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING
355 West North Temple
3 Triad Center, Suite 350
Salt Lake City, Utah 84180-1203
Telephone: (801) 538-5340
Fax: (801) 359-3940

ANNUAL REPORT OF MINING OPERATIONS

The informational requirements of this form are based on provisions of the Mined Land Reclamation Act, Title 40-8, Utah Code Annotated 1953, as amended, and the General Rules as promulgated under the Utah Minerals Regulatory Program. An operator conducting mining operations under a Notice of Intention must file an annual operations and progress report (FORM MR-AR) with the Division.

I. GENERAL INFORMATION

1. Report Time Period: From (mo./yr.) 1/93 To (mo./yr.) 12/93
2. DOGM File Number: M / 045037
3. Mine Name: Grantsville
4. Mineral(s) Mined: Salt (Sodium Chloride)
5. Legal Description (Location of Lands Affected):
 1/4, 1/4, Section , Township , Range
 1/4, 1/4, Section , Township , Range
 1/4, 1/4, Section , Township , Range
Morton International, Inc.
6. Name of Operator or Company: Morton Salt Division
7. Permanent Address: I 80 West, Exit 84
P. O. Box 506
Grantsville, Ut 84029

8. Company Representative (or designated operator):

Name: Gary C. Price
Title: Facility Manager
Address: 204 Country Club, Stansbury Park, Utah 84074
Phone: _____

☐ Please check if any of the above information has changed since previous year.

II. MINING AND RECLAMATION

1. Was the mine active during the past year? Yes ☒ No ☐

2. If active, how much ore or mineral was mined? 300,000

3. How much new or additional acreage was affected during past year? 0

4. Briefly describe any new or additional surface disturbances that occurred during the past year. This description should include the type of work performed, and volume of material moved.

Repair and maintenance of existing dykes.

5. How much acreage was reclaimed during past year? None

6. Briefly describe the reclamation work performed during the past year. This description should include methods employed, and an evaluation of the results.

None

7. What is the total disturbed acreage at years end? 15,000 acres
8. Briefly summarize mining and reclamation planned for the upcoming year.
We anticipate harvest of the same pond acreage annually.

NOTE: Section III., "Additional Information" applies only to large mining operations.

III. ADDITIONAL INFORMATION

1. An updated surface facilities map should be attached if there have been significant changes since the previous map was submitted.
2. Any monitoring results or other reports that are required under the terms of the approved notice of intention should also be attached.

IV. SIGNATURE REQUIREMENT

I hereby certify that the foregoing is true and correct.

Name (Typed or Print): Gary C. Price

Title of Operator: Facility Manager

Signature of Operator: 

Date: 1/21/93

jb
MR-AR

Location of Operation

County: Tooele

Township: 1N Range: 5W Section(s): 19

Township: 1N Range: 6W Section(s): 24, 25, 26, 32, 33, 34, 35

Township: 1S Range: 5W Section(s): 16, 19, 20, 21

Township: 1S Range: 7W Section(s): 1, 2, 3, 10, 11, 12, 13, 14, 15

Township: 1S Range: 6W Section(s): 2, 3, 4, 5, 6, 7, 8, 9, 10, 11,
13, 14, 15, 16, 17, 18, 19, 20,
21, 22, 23, 24, 25, 26, 27, 28, 29

SW
Morton International

Morton Salt

RECEIVED

FEB 01 1993

DIVISION OF
OIL GAS & MINING

January 29, 1993

D. Wayne Hedberg
State of Utah
Department of Natural Resources
Division of Oil, Gas and Mining
355 West North Temple
3 Triad Center, Suite 350
Salt Lake City, Utah 84180-1203

Re: Annual Report for Year 1992 - Morton Salt

Dear Mr. Hedberg:


Attached please find Annual Report for Mine M/045/037 Morton Salt.

An updated surface facilities map is not attached as there have not been any significant changes. Approval of the Notice of Intention is pending, and there are no monitoring results or other results that are required.

A written response advising whether this report is acceptable is requested.

Should you have any questions, please call 250-6335.

Thank you,



Lloyd M. Godfrey
Environmental Coordinator
Grantsville Facility

LMG:mb

Encl: Annual Report of Mining Operations for Mine
M/045/037 of January 21, 1993

cc: H. W. Diamond-Chicago (w/enclosure)

